



MAIL TO: P.O. BOX 16347 • Louisville, KY 40256-0347
 SHIP TO: 3649 Cane Run Road • Louisville, KY 40211-1961
 Tel: (502) 778-2731 • 1 (800) 928-PUMP

Visit our website:
 zoellerpumps.com

Product information presented here reflects conditions at time of publication. Consult factory regarding discrepancies or inconsistencies.

REPLACEMENT PARTS LIST FOR MODELS:

U803 AUTOMATIC 220V


V803 NONAUTOMATIC 220V

U805 AUTOMATIC 220V

V805 NONAUTOMATIC 220V


U807 AUTOMATIC 220V

V807 NONAUTOMATIC 220V



153223

WIRING DIAGRAM FOR MODELS
 "U803", "U805", "U807"
 All revisions



153224

WIRING DIAGRAM FOR MODELS
 "V803", "V805", "V807"
 All revisions

REPLACEMENT PARTS LIST FOR MODELS "U803","U805","U807","V803","V805", AND "V807"

				MODELS: U803-A U805-A U807-A	V803-A V805-A V807-A
REF. NO.	DESCRIPTION	QTY	NOTES	12/16 thru Current	12/16 thru Current
1	COVER ASSEMBLY - AUTOMATIC (CORD, 15' LENGTH SJOW NO PLUG)	1		156934	N/A
	COVER ASSEMBLY - AUTOMATIC (CORD, 15' LENGTH H07RN-F3G1,5; I PLUG)			154484	N/A
	COVER ASSEMBLY- NON-AUTOMATIC (CORD, 15' LENGTH SJOW NO PLUG)			N/A	156935
	COVER ASSEMBLY- NON-AUTOMATIC (CORD, 15' LENGTH H07RN-F3G1,5; I PLUG)			N/A	154485
2	• HANDLE	1		154989	154989
3	• RETAINER - NON-AUTOMATIC	2		N/A	267053
4	• GUARD - AUTOMATIC	1		267008	N/A
5	• ARM AND SEAL ASSEMBLY AUTOMATIC	1		004741	N/A
6	CORD SEAL ASSEMBLY - AUTOMATIC AND NON-AUTOMATIC (CORD, 15' LENGTH SJOW NO PLUG)	1		156933	156933
	CORD SEAL ASSEMBLY - AUTOMATIC AND NON-AUTOMATIC (CORD, 15' LENGTH H07RN-F3G1,5;I PLUG)			152015	152015
7	• CORD SEAL ASSEMBLY (CORD, 16-3 SJOW)	1		153747	153747
	• CORD SEAL ASSEMBLY (CORD, H07RN-F3G1,5)			151312	151312
8	SWITCH ASSEMBLY	1		004744	N/A
9	FLOAT ASSEMBLY	1		153748	N/A
10	• COVER GASKET	1		001011	001011
11	RUN CAPACITOR ASSEMBLY	1		154923	154923
12	START CAPACITOR ASSEMBLY	1		153750	153750
13	RELAY ASSEMBLY	1		153751	153751
14	• WIRE PACK - AUTOMATIC AND NON-AUTOMATIC	1		153752	153752
15	ROTOR & STATOR ASSEMBLY			157961	157961
16	IMPELLER ASSEMBLY - 803			153760	153760
	IMPELLER ASSEMBLY - 805			153761	153761
	IMPELLER ASSEMBLY - 807			153762	153762
17	ADAPTER	1		153151	153151
18	PUMP HOUSING	1		153152	153152
19	CUTTER ASSEMBLY	1		153763	153763
20	• DIELECTRIC OIL (40 OZ)	1		153764	153764
21	• BEARING SPRING	1		017192	017192
22	• BEARING - UPPER	1		006703	006703
23	• KEY - WOODRUFF	1		006841	006841
24	• BEARING - LOWER	1		010069	010069
25	• SEAL - MOTOR HOUSING	1		001014	001014
26	• SHAFT SEAL ASSEMBLY	1		011681	011681
27	• THRU WALL TERMINAL	3		003402	003402
28	• TEST PLUG	2		034090	034090
29	• SCREW 1/4-20 X 1 LONG	12		007790	007790
30	• SCREW #10-24 X 3/8 LONG	2	4	001883	001883
31	• SCREW #6-32 X 1/4 LONG - GREEN	4		001877	001877
32	• SCREW #6-32 X 7/16 LONG	3		004644	004644
33	• SEM SCREW #10-24 X 3/8 LONG	1		002000	002000
34	• SCREW #6-32 X 1/2 LONG	6		152866	152866
35	• SCREW #10-24 X 5/8 LONG	1	4	001884	001884
36	INSULATOR FLAG TERMINAL	2		001797	N/A
□	REBUILD KIT	1		154486	154486


• Items included in Rebuild Kit.

□ Not shown in illustration.

NOTES:

- 1) See FM0160 Parts Price Sheet for listing of parts prices.
- 2) "NA" indicates, not applicable.
- 3) If an "X" follows model no., or date Mfg. on ID tag, consult factory for ordering any parts.
- 4) Apply loctite thread locker #222.

REPLACEMENT PARTS ILLUSTRATION FOR MODELS "U803","U805","U807","V803", "V805", AND "V807"



NOTES



MAIL TO: P.O. BOX 16347 • Louisville, KY 40256-0347
SHIP TO: 3649 Cane Run Road • Louisville, KY 40211-1961
Tel: (502) 778-2731 • 1 (800) 928-PUMP
Trusted. Tested. Tough.®

Visit our website:
zoellerpumps.com